

---

# Bayswater – Mt Piper 5A3 500 kV line Trip and Bayswater No. 4 Generator Trip on 10 August 2021

---

**December 2021**

Reviewable Operating Incident Report under the  
National Electricity Rules

---

# Important notice

## PURPOSE

AEMO has prepared this report in accordance with clause 4.8.15(c) of the National Electricity Rules, using information available as at the date of publication, unless otherwise specified.

## DISCLAIMER

AEMO has made every reasonable effort to ensure the quality of the information in this report but cannot guarantee its accuracy or completeness. Any views expressed in this report may be based on information given to AEMO by other persons.

Accordingly, to the maximum extent permitted by law, AEMO and its officers, employees and consultants involved in the preparation of this report:

- make no representation or warranty, express or implied, as to the currency, accuracy, reliability or completeness of the information in this document; and
- are not liable (whether by reason of negligence or otherwise) for any statements or representations in this document, or any omissions from it, or for any use or reliance on the information in it.

## COPYRIGHT

© 2021 Australian Energy Market Operator Limited. The material in this publication may be used in accordance with the copyright permissions on AEMO's website.

## CONTACT

If you have any questions or comments in relation to this report, please contact AEMO at [system.incident@aemo.com.au](mailto:system.incident@aemo.com.au).

The National Electricity Market (NEM) operates on Australian Eastern Standard Time (AEST). All times in this report are in AEST.

# Abbreviations

<b>Abbreviation</b>	<b>Term</b>
<b>AEMO</b>	Australian Energy Market Operator
<b>AEST</b>	Australian Eastern Standard Time
<b>CT</b>	Current Transformer
<b>FOS</b>	Frequency Operating Standard
<b>Hz</b>	Hertz
<b>kV</b>	Kilovolt
<b>MW</b>	Megawatts
<b>NEM</b>	National Electricity Market
<b>NER</b>	National Electricity Rules
<b>REF</b>	Restricted Earth Fault
<b>TNSP</b>	Transmission Network Service Provider

# Incident review

This reviewable operating incident<sup>1</sup> report is prepared in accordance with clause 4.8.15(c) of the National Electricity Rules (NER). It has been prepared using information provided by Transgrid<sup>2</sup>, AGL<sup>3</sup> and from AEMO systems.

**Table 1 Simultaneous trip of Bayswater – Mt Piper 5A3 500 kV line and Bayswater No. 4 (BW04) generator**

	Details
<b>Reviewable operating incident type</b>	Non-credible contingency event impacting critical transmission elements.
<b>Incident details</b>	This report relates to a reviewable operating incident <sup>4</sup> that occurred on 10 August 2021 in New South Wales. The incident was a non-credible contingency event involving the trip and auto reclose of the Bayswater – Mt Piper 5A3 500 kilovolt (kV) and simultaneous trip of Bayswater Unit No. 4 (BW04).
<b>Incident classification</b>	Other causes – human error.
<b>Generation impact</b>	440 megawatts (MW) of generation was lost at 0306 hrs.
<b>Customer load impact</b>	No load was lost as a result of this incident.
<b>Pre-incident conditions</b>	Prior to this event, the Bayswater – Mt Piper 500 kV circuit was in service. At Bayswater Power Station, a 23/11 kV auxiliary transformer associated with BW04 was out of service for maintenance. BW04 was in service and following dispatch targets (see Figure 1).
<b>Incident key events</b>	<ol style="list-style-type: none"> <li>On 10 August 2021 at 0306 hrs: <ul style="list-style-type: none"> <li>Bayswater – Mt Piper 5A3 500 kV line tripped and auto-reclosed 17 seconds later.</li> <li>BW04 generator tripped from 440 MW.</li> </ul> </li> <li>At 2030 hrs Transgrid confirmed 5A3 Line tripped due to a fault on the line.</li> </ol>
<b>Incident cause</b>	Post-event, Transgrid confirmed that a fault had occurred on 5A3 line, approximately 89 km from Bayswater on the red phase. Terrain in the area of the fault is generally steep undulating terrain where no damage was found and no vegetation encroachment hazard was identified. The fault caused the trip and auto-reclose of the line. Simultaneously BW04 tripped unexpectedly due to operation of the unit's restricted earth fault protection.
<b>Power system response (facilities and services)</b>	<p>A fault on the red phase of line 5A3 caused protection no. 1 and protection no. 2 on line 5A3 to operate, tripping the line. Line 5A3 successfully auto-reclosed 17 seconds later. Transgrid has completed an aerial inspection of this circuit but has been unable to identify the cause of the fault. In addition, Transgrid's inspection did not identify any damage on the circuit.</p> <p>Simultaneously BW04 unexpectedly tripped due to operation of its Restricted Earth Fault (REF) protection. Prior to this incident at BW04, one of its 23/11 kV auxiliary transformers was in the process of being reinstalled. During these works, a Current Transformer (CT) from the de-energised transformer was incorrectly connected to an active protection system.</p>

<sup>1</sup> Reviewable operating incidents are defined by NER clause 4.8.15(a) and the AEMC Reliability Panel Guidelines for Identifying Reviewable Operating Incidents.

<sup>2</sup> Transgrid is a Transmission Network Service Provider (TNSP) for New South Wales.

<sup>3</sup> AGL is the owner of the Bayswater Power Station

<sup>4</sup> See NER clause 4.8.15(a)(1)(i), as the event relates to a non-credible contingency event; and the AEMC Reliability Panel Guidelines for Identifying Reviewable Operating Incidents.

	Details
	The incorrect connection resulted in a short between the B phase CT and the neutral phase CT at Bayswater. The 5A3 line fault caused a circulating current in the shorted CTs at BW04, causing the unit's REF protection to operate. This protection should not have operated for the external 5A3 line fault.
<b>Rectification</b>	Transgrid was unable to identify the cause of the 5A3 line fault, however this circuit's protection operated as per design to clear the fault.  Bayswater Power Station personnel identified and resolved the cause of the BW04 trip on 10 August 2021. The bridge between the two shorted CTs was removed prior to BW04's return to service. AGL also confirmed that the generator will not trip for similar events in the future.
<b>Power system security</b>	The power system remained in a secure operating state throughout this incident and the Frequency Operating Standard (FOS <sup>5</sup> ) was met for this incident. The minimum system frequency during this incident was approximately 49.83 hertz (Hz) at 3:06:55 and returned to above 49.85 Hz by 3:06:57 (see Figure 2).
<b>Reclassification</b>	AEMO assessed whether to reclassify this incident as a credible contingency event <sup>6</sup> . AEMO correctly did not reclassify this event as a credible contingency, as Bayswater Power Station identified the cause of the trip and rectified it before returning BW04 to service. The Bayswater team also advised that the unit will not trip for a similar type of fault.
<b>Market information</b>	For this incident, AEMO issued the following market notices (all market notices for this incident were issued in accordance with NER requirements): <ul style="list-style-type: none"> <li>• AEMO issued Market Notice 89358 at 0322 hrs on 10 August 2021 – Advice of non-credible contingency event – New South Wales region.</li> <li>• AEMO issued Market Notice 89371 at 2043 hrs on 10 August 2021 – Update – Non-credible contingency event – New South Wales region.</li> </ul>
<b>Conclusions</b>	AEMO has concluded that: <ol style="list-style-type: none"> <li>1. There was a fault on line 5A3 on the red phase which caused the trip and auto-reclose of the line. Transgrid has been unable to identify the cause of this fault.</li> <li>2. The trip of BW04 was caused by incorrect earthing configuration of an auxiliary transformer.</li> <li>3. The power system remained within a secure operating state throughout this incident and the FOS was met.</li> <li>4. AEMO correctly identified there was no requirement to reclassify this incident as a credible contingency.</li> </ol> <p>The cause of the BW04 trip has been identified and rectified by removing the bridge between two shorted CTs.</p>
<b>Recommendations</b>	AGL to review maintenance procedures to reduce the likelihood of similar events.

<sup>5</sup> The FOS can be accessed via <https://www.aemc.gov.au/australias-energy-market/market-legislation/electricity-guidelines-and-standards/frequency-0>.

<sup>6</sup> AEMO is required to assess whether or not to reclassify a non-credible contingency event as a credible contingency event – NER clause 4.2.3A(c) – and to report how the reclassification criteria were applied – NER clause 4.8.15(ca).

Figure 1 BW04 active power trace




Figure 2 Mainland frequency performance

