

## Verification and Testing of Facilities for the Purposes of the Reserve Capacity Mechanism

1 April 2009 to 30 September 2009

- Reserve Capacity tests were undertaken by System Management, on behalf of the IMO on the following facilities:

| Participant | Facility            |
|-------------|---------------------|
| NEWGEN      | NEWGEN_KWINANA_CCG1 |
| GLDFLDPW    | PRK_AG              |
| WPGENER     | PINJAR_GT9          |
| WPGENER     | PINJAR_GT7          |
| WPGENER     | PINJAR_GT5          |
| WPGENER     | PINJAR_GT4          |
| WPGENER     | PINJAR_GT3          |
| WPGENER     | PINJAR_GT2          |
| WPGENER     | PINJAR_GT11         |
| WPGENER     | PINJAR_GT10         |
| WPGENER     | PINJAR_GT1          |
| WPGENER     | KWINANA_G6          |
| WPGENER     | KWINANA_G5          |
| WPGENER     | TIWEST_COG1         |
| WPGENER     | KEMERTON_GT11       |
| WPGENER     | WEST_KALGOORLIE_GT3 |
| WPGENER     | WEST_KALGOORLIE_GT2 |
| WPGENER     | GERALDTON_GT1       |
| ALINTA      | ALINTA_WGP_U2       |
| ALINTA      | ALINTA_WGP_GT       |

System Management delayed the Reserve Capacity Test for the following Facilities due to the Facilities being on a Forced outage and could not be tested in accordance with clause 4.25.3A(b) of the Market Rules.

| Participant | Facility    |
|-------------|-------------|
| WPGENER     | PINJAR_GT9  |
| WPGENER     | KWINANA_GT1 |